


SeaCure 20" Surface Casing

Total – Ballindalloch



Challenges

Getting cement back to seabed, pressure testing casing against channelled displacement fluid through thixotropic cement in shoetrack and cement patio around WH

Solutions

The clinical execution of SeaCure Cementing service delivers low-risk, high-value cementing operations and casing hydraulic integrity solutions

